



# Lloyd's Register of Shipping,

LLOYD'S REGISTER,  
LONDON.

61, rue de la Bourse,

Havre, 2 January 1923

REC'D - 3 JAN 1923

The Secretary  
London.

S. S. "St. Boniface"

Dear Sir,

We beg to acknowledge receipt of both  
your cablegrams regarding the above named  
vessel and in reply have wired as follows:-

"Boniface at Cherbourg until February  
action taken with builders to verify valves  
excess pressure test not made. writing"

We learn that this vessel having sustained  
damage is undergoing repairs at Cherbourg  
and will remain there until the end of  
January.

With regard to the floating of the safety valves  
account was taken of the amount of  
accumulation of pressure but builders  
we agreed to afford us facilities for  
opening this when steam is raised just before

005180-005186-0138 1/2



Vessels' departure from Cherbourg

We have communicated with the builders regarding the design of the valves, the dimensions of which have not been checked by this office.

Letter from Mr Ward dated 10<sup>th</sup> Feb. 1922 accompanying a plan of 5.5<sup>in</sup> Safety Valve received by London Office, it was stated these valves met the requirements of rules except in respect to the aggregate but the deficiency being so small were considered to be satisfactory.


We understand that the valves which were are 7.0<sup>in</sup> diam. but we shall confirm as soon as possible.

We are, Sir,

Yours faithfully

The Surveyors

per *J. H. Davies*



© 2020

Lloyd's Register Foundation

0138 2/2



-3 JAN 1923

To await further letter  
from the Haver sugar.

A. H. B.

4/1/23

© 2020

Lloyd's Register  
Foundation