

15 JAN 1968

Ship's name "GRIFONE"Port

Alx

No. 7087Last survey date 7.12.67

Class is subject to temporary repairs to fractured shell plating in 2nd strake below sheer (p.amids) also to sheerstrake etc. in way of E.R. (p) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before ~~xxxxxxxxxxx~~)

Surveys due SPECIAL SURVEY (C) due 12,66. Postponement until 12,67 approved 20.3.67. G.E. held Nap. 2,67.

Nature of present survey (afloat ~~xxxxxxxxxxxx~~)

Deferment of ranging damage.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by 12,67

TO NOTE		TRO
S. PLANS	S. RESEARCH	S. DEVELOP.
FREEDBOARD	E. REPORTS	PUBS.


Recommendation

SUBMITTED ACTION continue to be DEFERRED for S.S. by 12,67, subject as above, and to top edge of poop sheer etc. (s.a) poop deck guard rails (p) after docking bridge (p& s) being specially examined and dealt with as necessary by the S.S. also to mooring ropes being brought up to Rule by the S.S.

SUBJECT

IN S.R.L. APPENDIX

(Stem bar buckled at 11' draught mark)
Bottom shell plate B.2 (p.f) indented.



© 2020

15/1/68
Lloyd's Register
Foundation