

LLOYD'S REGISTER OF SHIPPING



al

Port NaplesDate 13th February 1967

This is to Certify that I have surveyed part of the machinery of the S/S "GRIFONE" 6724 gross tons of Naples for MBS and General Examination for postponement of ES, whilst lying afloat at this Port on the 6th February 1967 and subsequently

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned MBS (with date) when the survey has been completed and to have the Engine Special Survey (due 12/66) postponed until some-time before 12/67, subject to any outstanding conditions at present attached to her class being dealt with as previously recommended.

Parts now examined:—For General Examination

- Pumping arrangement
- Megger test of electrical equipment
- Machinery working
- Some parts of machinery opened up for maintenance routine.

For MBS

- Port boiler throughout with valves and fittings, and safety valves adjusted under steam.
- Oil burning system and remote controls examined working.

To complete the MBS, the starboard and centre boilers remain to be examined throughout and their safety valves adjusted.

(P. Arena) 

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers, Servants or Agents of the Society."