

Ship's name "PHOENICIAN STAR"

Port

Yka 6539
Hak. No. 1137

Last survey date 7.4.66

Class is subject to

For conditions of class see previous endorsement.

ACTION is DEFERRED for S.S. by 8,66.

S.R.L. Appendix (~~as before~~ none)

Surveys due SPECIAL SURVEY (C) due 8,65. Postponement until 8,66 approved 24.1.66.

Nature of present survey (afloat ~~and in drydock~~)

Temporary wear and tear repairs to shell plating.

Is interim certificate in order

Yes/~~No~~/~~None~~

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by

8,66.

Recommendation

SUBJECT to renewed stringer plating over midship deep tank (p & s) and forward E.R. bulkhead in way being tested by the S.S. and not subjected to pressure in the meantime, and to shell plates Nos.8 & 10 in 1st below sheer (s. from f.) (doubled) ~~being~~ also to temporarily repaired shell plate H.7 (p.a) in way No.5 hold and G.1 (p.a) in way store space being specially examined and dealt with as necessary by the S.S. but ACTION continue to be DERERRED for SS by 8,66.

SUBJECT
AMENDED.

TO NOTE		TRO
S. PLANS	S. RESEARCH	S. REPORT
PREBOARD	E. REPORTS	IPDS