

COPY OF AIR LETTER

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

14th May, 1965.

R  
SEI/CB

Dear Sirs,

n.s. "SAN FERNANDO"

With reference to my letter of the 9th April, I shall be glad if you will confirm for the information of the Committee that definite arrangements have been made to carry out the long overdue Screwshaft Survey at a Japanese port before the end of the present month.

It think it well to add that the hull class is at present continued subject, inter alia, to the shell plates in "H" and "J" strakes in way of frames 68 (port side) and 71-73 (starboard side) and upper deck plating in way being permanently repaired at the drydocking in Japan, also to set in shell plates H.8 and 9, J.8 and K.9 (starboard side from aft) together with framing in way being specially examined and dealt with as necessary at the next drydocking.


Your attention is drawn to the Special Survey which will become due at the end of August, 1965.

It will be appreciated if you will forward a copy of your reply to the Society's Surveyors at Hong Kong.

Yours faithfully,

Clerk to the  
Classification Committee

Messrs. Manners Navigation Co. Ltd.,  
P.O. Box 235,  
HONG KONG.



© 2020

Lloyd's Register  
Foundation

005187-005193-0297