


LLOYD'S REGISTER OF SHIPPING

Port LIVERPOOL.Date 23rd March, 1965.

This is to Certify *that I have surveyed part of the machinery of the* **s.s. "SYCAMORE HILL" 7126 gross tons of London** *for Docking, Damage, Commencement of Engine Survey, Completion of Main Boiler Survey, and Tail Shaft Survey, whilst the vessel lay in drydock at Birkenhead on the 8th March, 1965 and subsequently, and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following* **E.S. (with date) on completion, survey records assigned M.B.S. 2,65 (previously recommended) now, T.S.C.L. 3,65 without condition of class regarding the propeller and underwater fastenings and subject to any outstanding conditions of class being dealt with as previously recommended.**

Parts now examined:—

Propeller, underwater fastenings and sea valves.

Tail Shaft.

For Commencement of Engine Survey.Main Engine.

H.P., I.P. and L.P. guides.

L.P. Ahead and Piston eccentric straps and sheaves.

Auxiliaries.

Ballast Pump.

General Service Pump.

Main Circulating Pump (water end only).

Feed Water filter tanks.

Forward steam driven generator engine.

P.T.O.

A. Jackson
Surveyor to Lloyd's Register of Shipping
A. Jackson.

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

LLOYD'S REGISTER OF SHIPPING

For Completion of Main Boiler Survey.

Port and Centre Boilers throughout.
Port, Centre and Starboard Boilers examined under
steam and their safety valves adjusted.
Oil fuel installation and Remote Controls.



© 2020

Lloyd's Register
Foundation