



MEMORANDUM

22 JAN 1958

DEC 14 1957

LOYD'S REGISTER OF SHIPPING,

71, FENCHURCH STREET,
LONDON, E.C.3.

(Ref. H.)

Surveyor(s) at **HALIFAX, N.S.**Date: **11th December, 1957.**Name: **m.s. "SHEILA PATRICIA"**

IX PPR

QUESTION

ANSWER

With reference to your
t. No. 7272, I shall be glad
to learn what arrangements
are proposed to be made for
the indented stem plating to
be dealt with, as recommended.

[Signature]

Date:— December 30, 1957

Owners have requested that
permanent repairs be deferred
until next drydocking.

Vessel was re-surveyed on
26th December, 1957 at Mulgrave,
N. S. and a report will follow
as soon as possible.

© 2020

Lloyd's Register
Foundation

005194-005209-0105

Sheila Patricia
Mr Buchanan