

005210 - 005218 - 0088

4E

Class expunged 10.57.


Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor... 16 OCT 1958

SHIP'S NAME..... REMEDIOS..... REPORT Bel..... N837

Re-classification Survey commenced and both main engine crankshafts found cracked, also some connecting rods and crossheads and it was decided to suspend the survey and put the vessel up for sale.

It is noted in Barcelona letter of 22.9.58, that the vessel has been sold for beaking up.

IT IS SUBMITTED no further action necessary.



© 2021

Lloyd's Register  
Foundation

110 OCT 1958

21 CLUTCHES &amp; HYDRAULIC COUPLINGS.....

22 REDUCTION GEARING.....