

Sheer at Stem Bar ..... 94".

17.25  
11 3/4  
11 3/4

should be rep  
ed on the  
breadth of ve  
at the gunwale.

REPORT on the *Sis. W. G. Armstrong, Whitestar & Co's Motorship No. 984*

The Surveyor should be requested to report when forwarding the final report.

(1) The tonnage between the upper edges of the transverse floors in way of the deep water ballast tank forward and the continued line of the upper surface of the longitudinals.

(2) The tonnage between the double bottom tank top aft and the continued line of the upper surface of the longitudinals.

GKM

S. W. B.

28. 4. 20.



© 2021

Lloyd's Register  
Foundation

005210 - 005218 - 0111

Shipping measured