

"ACCRA" & "APAPA"

Req. 13.

(Received at London Office.....19.....)

No. Port BARROW-IN-FURNESS Date 12th FEBRUARY 19 46

WE request that the Refrigerating Machinery and Appliances of the Steam Motor Ships building by VICKERS-ARMSTRONGS LTD for ELDER DEMPSTER LINES LTD.

Builders' Yard No. 948 & 949 may be specially surveyed during construction with a view to the notation RMC (in red) (i.e., Refrigerating Machinery Certificate) being made in the Register Book.

The vessel is.....intended for Classification in Lloyd's Register.

WE hereby engage to pay the established scale of fees, or any variation therefrom which has duly notified.

In exceptional cases an additional charge will be made according to the service performed, and in all cases where travelling expenses are incurred by the Surveyors in connection with the above services, they are to be defrayed by the parties involved.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Manufacturers of Refrigerating Machinery J & E. HALL LTD, DARTFORD IRON WORKS, DARTFORD, KENT.


FOR VICKERS-ARMSTRONGS LTD.

Signature.....
[Signature]
SHIPBUILDING-MANAGER,
BARROW, WORKS.

To the Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."



Lloyd's Register
Foundation
005258-008553-013

and manhole doors of tanks none Are insulated plugs fitted to ventilators yes cargo ports none