

34009

30 APR 1956

Rpt. C. 11 (Contd.)

Index No.

Lloyd's Register of Shipping.

Ship's Name **s.s. " HILARY "**

Official No. **162350.**

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in **1932.**

All steel hatchcovers of N^o. 1 hatchway on forecastle deck, N^os 2 & 4 hatchways on upper deck and 50% of the steel hatchcover of N^o.5 hatchway on upper deck have been dispensed with and replaced by wood hatchcovers 3" thick.

The four ventilators on upperdeck for the N^os 4 & 5 tweendeck refrigerated cargo spaces (see Ant.Rpt. C.11 Contd.N^o.30998) are fitted with screwed down W.T. mushroom tops.

[Handwritten signature]

N Steel
JH
10.5.52



© 2021

Lloyd's Register Foundation

005307-005310-0097