

13 AUG 1942

Index No.

34009

Lloyd's Register of Shipping.

Ship's Name

HILARY

Official No.

162350

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines
in 1932

Accommodation has now been provided, at the aft end of N°1 upper tween deck, on the port side, for 24 stewards.
7 additional port lights fitted to shell plating, 12" in dia^r complete with deadlights.

Companion for access (& escape) fitted to upper deck p.s.
Companion of substantial steel construction, plating .35" suitably stiffened. Sill 21" above wood deck with heavy teak door operated from both sides.

Noted

13/8/42

E. Little

8/8/42



© 2021

Lloyd's Register
Foundation