

C O P Y

HULL

9th November, 1949 ✓

H

Dear Sir,

M.V. "JIM M"

Ref:

F.

With reference to our Reports 8, No. 56094, and C11(c), No. Fbd. 3287, recently submitted in respect of the above vessel, we think it well to explain that, at the time the Load Line Certificate was issued, the Owners stated it was their intention to carry out the testing of the oil fuel bunkers in completion of the Special Survey before the vessel sailed. Owing to a change in their commitments, however, they failed to adhere to this arrangement and as the existing Load Line Certificate had expired it was not considered the circumstances warranted withdrawal of the fresh certificate.

We have the Owners' assurance that the Oil fuel bunker testing will be dealt with at the first available opportunity.

Yours faithfully,

The Surveyors.

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

005311-005317-0079

Handwritten notes:
Had 9/11 H 12 1/11