

005311-005317-0085

23 NOV 1949 E

Used by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SSE'S NAME

JIM M.

REPORT

Hul.

No. 56094.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

ure of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S-S-NO.

This Survey, due 9,48 now  
partly-held

new-

~~completed~~, and the following repairs carried out (due to wear & tear):-

A new screw shaft fitted.

The two auxiliary engine removed from vessel and replaced by two reconditioned ones, all main engine cylinder liners renewed.

One piston and all gudgeon pins renewed.


Alterations: Pumping arrangements have been modified in accordance with approved plans.

It is submitted the vessel is eligible to remain as classed, with

notation of

MBS 10,49  
S N 10,49

as recommended.



© 2021

Lloyd's Register  
Foundation  
23.11.49.