

MEMORANDUM

COPY

From : LLOYD'S REGISTER OF SHIPPING,
SOUTHAMPTON

71, FENCHURCH STREET,
LONDON, E.C.3.

(Ref. H.)

25th October, 1960

To : The Surveyor(s) at

s.s. "ST. HELIER" and "ST. JULIEN"

Date:

Vessel's Name:

24/12
10/11/60

QUESTION

ANSWER

With reference to
your letter of the 5th
and my reply of the 12th
August, I shall be glad
to learn how these cases
now stand.

Date:

31st October, 1960.

Owners now inform us that they
do not intend to fit the new crank-
shafts, which are available onboard
each vessel, as these vessels are
to be taken out of service for
disposal.



© 2020

Lloyd's Register
Foundation

005321-005324-0128

7.6.60

7.60 extended to 9.60

NOT

as vessel the

disposed of

Await further information

Sub
8/11/60

© 2020

Lloyd's Register
Foundation