

REPORT of SURVEY for REPAIRS, &c.

Report: 5th June 1920 When handed in at Local Office: 5th June 1920 Port of: Gothenburg
Survey held at: Gothenburg Date, First Survey: 4th June Last Survey: 4th June 1920
on the Wood, Iron Steel: L.G. "Lombardia" (No. of Visits)
Master: C. Crafoord
PAGE:— Built at: Hansasveert By whom: "Zeeland", Werf When: 1920 MONTH: 5
2201 Owners: Rederikkehobolaget Svenska Lloyd Port belonging to: Gothenburg
2035 Owners' Address
1283 (if not already recorded in Appendix to Register Book).

Is the Vessel afloat or in Dry Dock? Afloat Name of Dock: Destined Voyage:
ULLDBorDBa feet; uE&B feet; f feet; }
Capacity tons. FPT tons; APT tons; MT feet tons. }
All alterations in the existing records should be underlined.

Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Report, No. Port

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from repairs due to other causes; repairs being detailed in the body of the report, should be summarised in the form shown below. Whenever the condition of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?

Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR: Compd. 1st Entry

Ash shroud renewed, tested with water pressure and light.

Please see Rotterdam Surveyor's 1st Entry Report on vessel.

At the request of the Owners a survey was carried out on this vessel from 6-9 a.m.

DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
and Faired or Repaired								
or Repaired in place								
CONDITION OF THE								
Stringers					Dblg. Plates under Sounding Pipes		Copper, or Y.M. of Wood Vessels	
Inner Bottom Plating					Engine Room Skylights		(State if on Felt.)	
State if Tanks have been examined inside					Coal Bunkers, Openings, Lids, &c.		When put on, Month	
State if Tanks now tested					Scuppers		Year	
Bulkheads					Cargo Hatchways		Boats	
Ceiling					Hatches		Masts, Yards, &c.	
Cement or Asphalt					Planking of Wood Vessels		Condition, how ascertained	
Rudder					Caulking ditto		(State if wedges removed)	
Steering gear and its connections					Treenails ditto		Sails	
Windlass					Breasthooks & Stemson ditto		Equipment letter	
Have Pumps now been examined and found efficient?					Transoms, Pointers, & Crutches ditto		Anchors, No. of	
Have Sluice Valves now been examined and found efficient?					Timbers of Frame at openings ditto		Cables (State if now ranged)	
Have Watertight Doors now been examined and found efficient?					Ditto ditto at other places ditto		length size	
					Stringers, Clamps & Shelves ditto		(on board)	
					Salting ditto		Rule length size	
					(State if examined.)		Hawser & Warps	
							Standing & Running Rigging	

Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of ss No. 1-15," or "to remain as classed and to have record of survey, 1, 15, and the notations of ss No. 1-15 and ptND15, &c."

This vessel is worthy in my opinion to be classed in the Society's Register Book without special conditions.

per Section 28) £ 50.00 : Fees applied for, 5th June 1920
Age or Repair Fee (if any) £ : Received by me, 19
Expenses (if chargeable) £ 5.00 :
Surveyor's office hours £ 10.00 :
Surveyor's Fee (if any) £ :
TUE. JUN. 15 1920
Surveyor to Lloyd's Register of Shipping.

Committee's Minute See minute on First Entry report

005358 - 005366 - 0189