

CARRIER.

500 20334.

attention of E. Dept.

Plans for the Crankshaft, Stem Valve
or popper shafting mentioned in 500 letter of 5/1/50
has not yet been approved.
is should be done before the case can be
and endorsed.

Engine Plans dept. should be asked whether
in aid of the shafting as given on Apr 4 complies
with Rules, as these sizes differ from those
in Sec letter of 124-3-49.

J. S. 14-8-50.

005367-005376-0168