

COPY.

Sha 1801

Lloyd's Register of Shipping.



Port

1st May, 1942.

This is to Certify that

the undersigned Surveyor to this Society did at the request of

the Owners' Managers make an examination as part of the Annual Load Line Survey of all wood hatches and did verify the freeboard markings cut in the vessel's sides.

The following hatches have been recommended for renewal, which renewals the Owners propose to carry out at a United States Port on arrival from Hull, from which port the vessel is to proceed in ballast:-

No. 1 hold upper deck.
Fore bay. 3 hatches 9ft. 4"
Middle " 2 " 9ft. 3"
Aft " 2 " 9ft. 2"

No. 2 hold upper deck.

Fore bay. 2 hatches 9ft. 4"
Middle " 2 " 9ft. 3"
Aft " 2 " 9ft. 2"

No. 3 hold upper deck.

Fore bay 1 hatch 9ft. 4"
Aft bay 3 hatches 9ft. 2"

Fore bay 1 hatch 9ft. 2"
Middle " 2 hatches 9ft. 3"
Aft " 1 hatch 9ft. 4"

No. 5 hold upper deck.

Fore bay 1 hatch 9ft. 2"
Middle " 2 hatches 9ft. 3"
Aft " 2 " 9ft. 4"

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its officers or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.

cont.

COPY

No. 1 hold 'tween decks (Freeboard deck)

Fore bay	4 hatches	9ft. 5"	3" x 19"
Middle bay	9 "	9ft. 3"	" "
Aft	6 "	9ft. 3"	" "

No. 2 hold 'tween deck.

Fore bay	8 hatches	9ft. 4"	3" x 19"
Middle "	5 "	9ft. 2"	" "
Aft	6 "	9ft. 3"	" "

No. 3 hold 'tween deck.

Fore bay	4 hatches	9ft. 4"	3" x 19"
Middle bay	4 "	9ft. 3"	" "
Aft	3 "	9ft. 2"	" "

No. 4 hold 'tween deck.

Fore bay	4 hatches	9ft. 3"	3" x 19"
Middle "	5 "	9ft. 3"	" "
Aft	3 "	9ft. 5"	" "

No. 5 hold 'tween deck.

Fore bay	5 hatches	9ft. 2"	3" x 19"
Middle "	5 "	9ft. 2"	" "
Aft	4 "	9ft. 5"	" "

A total of 101 hatches.

In addition to the above renewals, to complete the Annual Load Line Survey all freeboard requirements remain to be attended to with the exception of the verification of the freeboard markings, which has been done.

P. R. Sudd

THE REGISTER OF SHIPS

No. 3 hold upper deck.

Fore bay	1 hatch	9ft. 4"	3" x 19"
Aft	3 hatches	9ft. 2"	" "

N. B. The original of this certificate has been placed on board vessel for the information of the Surveyors at the United States to which the vessel will proceed.

P. R. Sudd

No. 2 hold upper deck.

Fore bay	1 hatch	9ft. 2"	3" x 19"
Middle "	2 hatches	9ft. 3"	" "
Aft	2 "	9ft. 4"	" "

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed and that the vessel is under any circumstances held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors or in any other Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Surveyors, or other Officers or Agents of the Society.

© 2021 Lloyd's Register Foundation