

COPY

LLOYD'S REGISTER OF SHIPPING

5575

Port D J A K A R T A

4th February 1959,

PART

This is to Certify *that I have*

Surveyed the ~~Boiler~~ and Machinery of the s.s. "WILLIAM CHARLICK
4", 4259 Tons Gross of Hong Kong, on the 30th January 1959
and subsequently, whilst afloat at Tandjong Priok,

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have

Recommended that the ~~record~~ of MACHINERY
remain as Classed,

made in the Register Book in the case of this vessel subject
to the main circulating pump being examined on arrival at
Hong Kong (February 1959).

(J.A. Boater).

Engineer Surveyor to Lloyd's Register

certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be
that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any
in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society,
error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents
ety."