

Lloyd's Register of Shipping.

MERCHANT SHIPPING (SAFETY AND LOAD LINE CONVENTIONS) ACT, 1932.

RENEWAL SURVEY IN ACCORDANCE WITH SECTION 48 (4) OF THE ABOVE ACT.

(Port) WELLINGTON
(Date) 22nd October, 1940

I have to report that I have surveyed the M. V.
"ARMADALE" of LONDON O.N. 161299

on this date.

I have compared the arrangements on board the ship with those given in the original freeboard report and I have found them to be in agreement therewith or equivalent thereto, and the whole to be in efficient condition.

Repairs:

No.1 Hatch coamings were brought back to their original good condition. 2 Beams renewed, several faired as required. Rest bars, battens and cleats renewed or replaced as required. 120 New wooden hatch covers supplied and fitted. Balance of hatches 12 new wood hatch covers supplied; all covers on all hatches in place and hatches battened. Tarpaulins good and in sufficient numbers also adequate supply of wedges.

The freeboard marking has been verified and found to agree with the freeboards given on certificate No. 12267 dated 28th December, 1937

which ~~is returned herewith~~ remains on board endorsed on Page 2 "I have surveyed this ship for the purpose of seeing whether this Certificate should remain in force and the survey has been completed to my satisfaction."
(Copy Certificate also endorsed as above.)

Sam. D. Linnett
Surveyor to Lloyd's Register.

Fee £5. 0. 0.



© 2021

Is fee paid

Lloyd's Register Foundation