

18½, Regent Quay,

ABERDEEN.

4th August, 1924.

The Secretary,

LONDON.

Sir,

LLOYD'S REGISTER
Recd. 5 AUG 1924
Ans'd
LONDON

Replying to your classing letter "S" August 1st, 1924, with reference to the S.S. "St. Magnus", Aberdeen report No. 13615, I beg to state, that the depth of the Centre Girder is 33" as mentioned on the Report, and that the thickness of the side girders as fitted is .32. The Shell landings are also as per report.

A copy of the letter approving same is attached. I note your remarks re spacing of rivets in landing edges, also that the depth from the top of the floors to the top of the beams should be taken at the centre line, and not at the deck at side, and will in future cases be guided thereby.

I am, Sir,

Yours faithfully,

J. Richardson

1 Enclosure;



© 2020

Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor.

5 AUG 1924

Hotel
51/5/24

© 2020

Lloyd's Register
Foundation