

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 19__

Lloyd's Register of Shipping.

(Report on Machinery, No. _____ Port _____)

No. V18248

ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured by Bockhorns Ltd. of Gardnald.

for the Engines or Boilers No. 1456/9 being constructed by Swan Hunter & Wigham Richardson Ltd. of Wallsend.

have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects.

These have been despatched to Wallsend.

Stamp Mark.

LLOYD'S TEST.	
<u>400</u>	lbs.
No. <u>12-6-34.</u>	<u>J.H.L.</u>

W. Scott.

Glasgow.

Number and Description.

4- 2 1/2" C.I. Improved High Lift Double Spring Safety Valves.

Hydraulic Test: lbs. per square inch.

400

Other Tests, if any.

✓

Date when Inspected.

12-6-34.



© 2020

Lloyd's Register
Foundation

005412-005423-0091

Working Pressure

202 lbs./sq. in.

Main stays: Material

Steel

Tensile strength

28