

12 NOV 1962

Ship's name *COHWYN BAY*

Port

*Hol.*No. *68 161*Class is subject to *NIL.*Last survey date *19.10.62.*

Docking, screw shaft examined, w D  $\frac{1}{8}$  & now  
re-wooded. Liner worn thin and  
S.W. recommends it be again examined  
by 10.63 (12 mos).

Bronze propeller broken at tips and now  
replaced by C.I. spare.

MBS due 11.62 now held.

Some plain tubes renewed, centre piece  
cropped locally & part-renewed. Back end  
plate SW at wastage in way of main cheek.

It is submitted that this  
vessel is eligible for THE  
RECORD. MBS 10.62 now.

Subject to the screw shaft liner (worn)  
being specially examined by 10.63 (12 mos)  
Record withheld.