

Received from Chief Surveyors.....

Chief Surveyors.....

SHIP NAME "MATA HARI"

REPORT.....

No.....

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

of Survey..... When due .....

This ship is classed BS "For Service in the Indonesian Archipelago".

The class is subject to repairs to shell plate in way of E.R.(p.s.) at the Special Survey.


A SPECIAL SURVEY(C) became due 12,55. Postponement of Special Survey until 6,56 approved.

In a memo dated 15.8.56 the DJAKARTA Surveyor advises that this ship is still operating and has been issued with an extension certificate by the Harbour Master of Palembang. In view of this the Surveyor at Djakarta recommends the ship's class be expunged from the Society's Register Book.

IT IS ACCORDINGLY SUBMITTED for the consideration of the Committee whether the class of this ship be expunged on account of non-compliance with regulations.

INSERT IN R.B.

Class withdrawn -  
non-compliance with regulations.



© 2020

Lloyd's Register

Foundation

005424-005435-0174

22  
8  
56