

EA

23 APR 1963

Ship's name "MARWARRI" Port ANT. No. 38678
Class is subject to Last survey date 27.3.63.

For conditions of class see previous endorsement.

S.R.L. Appendix (as before or ~~none~~)

Nature of present survey (afloat and ~~in drydock~~)

Examination of part deferred item as above.

Recommendation

SUBJECT to keel plates Nos.2 & 3 forward (set up) and indented shell plates Nos.5 & 6 in 3rd strake below sheerstrake, Nos.4 & 5 in 4th strake below sheerstrake (s.s.f) and to No.4 hold deep tank after bulkhead (corroded) in way of port bilge ~~being specially examined and dealt with as necessary~~, and to shell plate J.19 (corroded and leaking) (p.s.) ^{T20} being specially examined and dealt with as necessary next drydocking.

As Now Subject
amended.

IN S.R.L. APPENDIX

No.3 keel plate from forward slightly set up.



© 2020

Lloyd's Register
Foundation