

REPORT OF SURVEY FOR REPAIRS, &c.

Writing Report 9th Jan. 42 When handed in at Local Office 19... Port of SOURABAYA, JAVA.

No. in Survey held at Sourabaya Drydock Company Date, First Survey and Last Survey 6th Jan. 1942.

Book. 83454. on the ~~Wood~~ ~~Iron~~ Steel sc. ss. "SINGKEP" (No. of Visits 1)

TONNAGE:— Built at Amsterdam By whom Nederl. Schps. Maats. When 1922

GROSS 6607 Owners N.V. Stoomv. Maats. Nederland Owners' Address (if not already recorded in Appendix to Register Book)

UNDER DK. 4575 Managers - Port belonging to BATAVIA

NET 4070 Surveyed Afloat or in Dry Dock? in dock Name of Dock "Soerabaia" Destined Voyage

ell DBor DBa - feet; uE&B - feet; f - feet Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

total capacity - tons. FPT - tons; APT - tons; MT - feet - tons. Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined. Last Report, No. Port

CHARACTER. for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Survey (Including date of N.B., if any).
100 A1 (Class Contemplated) Exp'd 6.41 6.41	BS. 6.41 CL

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

Vessel placed in drydock, bottom and rudder cleaned, examined and found in good condition and recoated.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Fett.)
Decks	good	-	good	--
Walking of Decks	,,	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Stairways	,,	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	,,	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	,,	Steering gear and its connections	Cargo Hatchways	Condition, How ascertained (State if wedges removed.)
Frames	-	Windlass	Hatches	Equipment letter
Reverse Frames	-	Have pumps been examined and found efficient?	Planking	Anchor, No. of 3 B. 1 S.
Longitudinals	-	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged) no
Transverses	-	Have Watertight Doors been examined and found efficient?	Treenails	length mean diamr. (on board)
Floors	-	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemcon	Rule length size
Keelsons	-	Air and Sounding Pipes	Timbers of Frame at openings	Chain Locker
Stringers	-	Doubling Plates under Sounding Pipes	Stringers, Clamps & Shelves	Hawsers & Warps good
Inner Bottom Plating	-		Salting (state if examined.)	Standing and Running Rigging
Have the Tanks been examined internally? NO				Sails
Have the Tanks been tested? NO				

General Observations, Opinion as to Class, Recommendation, &c.:


State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— to remain as classed in the Register Book without "fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Vessel to remain as classed, with fresh record of survey Sba.1.42, subject to starboard after sanitary discharge being renewed at first opportunity. (Class Contemplated)

Survey Fee (per Section 20)	E. 80,00.:	Fees applied for, 8/1/42. 19
Special Damage or Repair Fee (if any) (per Sec. 20)	£	Received by me, 8/1/42. 19
Travelling Expenses (if chargeable)	E. 5,00.:	
Surveyor's Fee (if any)	£	

Signature of Surveyor to Lloyd's Register of Shipping.

Committee's Minute
Character Assigned 1, 42 Sba



Is Certificate required? If so, to be sent to Owners' address