

forced Thickness of cylinder liners 40%

Are the cylinders fitted with safety valves yes

Are the exhaust pipes

Engine
Boiler

No.

691120

Made by

M.A.N.

For

Deutsche Werke

No 182

Brun

Report No.

1809

It is submitted that a copy of this Report be
forwarded to the Ham Surveyors for their
returned guidance and for completion.

Date

7.8.36

Lloyd's Register
Foundation

005480-005488-0200

Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times.

1m, 6, 36.

Await Ham Rpt.
(Copy Rpt Sent)

Mr Cooke



© 2020

Lloyd's Register
Foundation

Identification Mark 10 5074 2/236 Intermediate shafts, Material S.M. Steel, Identification Marks 10 286 2/236.