

180-8

SURVEYORS

PHONE NO. BW 7023
P.O. BOX 338 F

Proportions—Depth to Length—Uppermost con- 1/2 S 1000 of Registry

Lloyd's Register of Shipping.

4 BRIDGE STREET.

SYDNEY, 20th January 1934.

N.S.W.

The Secretary,

Sir,

I beg to confirm my Radiogram to you of the 19th instant, which decoded, reads:-

"NALPA" VESSEL HAS BEEN MAINTAINED IN GOOD CONDITION DECKS
DRILLED .27 RAISED QUARTER DECK STRINGER .33 ARE THEY
ACCEPTABLE URGENT:

To which you replied even date:-

"NALPA" THICKNESSES REFERRED TO IN YOUR CABLE OF 19th
INSTANT WILL BE APPROVED PROVIDED SECTIONAL AREA MEETS
REQUIREMENTS OF THE RULES TABLE 20.

This matter is now receiving attention.

The cost of the above radiograms will be recovered from
the Owners at this port.

I am, Sir,

Your obedient Servant,

A. C. Heron

© 2020

Lloyd's Register

005518-75528-0115
Foundation

Referred to the Chief Ship Surveyor,

Also for Mr. Carey to note.

26 FEB 1934



© 2020
Lloyd's Register
Foundation