

Urgent

S.S. "NALPA", No. 31571 in the Register Book.  
-----

On the 17th instant the Society's Surveyors at Sydney, in reply to a cablegram, were authorised to undertake the survey of this vessel, which has never been classed with this Society, with a view to classification.

A further cablegram has to-day been received reading as follows :-

"Nalpa vessel has been maintained in good condition  
"decks drilled .27 raised quarter deck stringer .33  
"are they acceptable urgent."

It is submitted that they might be informed in reply that the thicknesses stated will be approved, provided the sectional area meets the requirements of Table 20 of the Rules.

19. 1. 34.



© 2020

Lloyd's Register  
Foundation

005518-005528-0120