

RD REPORT on the

S.S. "Cheribon marn".

The Surveyor should be requested to state the depth of the hatch webs, this information having been omitted on his report.

and dimensions
of the hatchways

W.D.

9.5.21

GRM



© 2020

Lloyd's Register
Foundation

005524-005536-0523

the following alterations were made.

6.94