

18 MAY 1917

t to Chief Surveyors 18. 5. 17.

Received from Chief Surveyors

VESSEL'S NAME

s/s

"White Ear"

Report

Hull

No. 29942^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Screw Shaft.

When due

10. 16

The 1st biennial examination of the screw shaft became due in 10. 16.

In reply to the usual notice to the Owners they now inform the Hull Surveyors that they do not wish to continue the class of the vessel.

It is submitted that the vessel's class be omitted from the ensuing edition of the Register Book.



© 2020

Lloyd's Register
Foundation

005537-005551-0094