

3 NOV 1920

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sc. "COMMANDANT DORISE". Rpt. Lon. No. 83641a**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Marseilles Surveyors state this vessel is undergoing extensive repairs on account of damage through fire. They add they have not been called in and have been informed by one of the Principal Representatives of the Owners that it is not their intention to continue the class of the vessel in the Society's Register Book.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at the Owners' request.

Withdraw class

Insert (...)

© 2020  
2. 11. 20.Lloyd's Register  
Foundation