

Hull Rpt N° 13907
cp "Lamport".

It is submitted, that the Hull Surveyors
should be requested to state the pressure to
which the safety valves were adjusted &
whether Easing gear has been fitted as
is not stated on their report.

See wire
in reply



© 2020

ARSL

Lloyd's Register
Foundation

005585005601-0174