

No. 93065.

005635-005643-0019



Starboard bow

B stroke No 1 plate removed, faired, and refitted.

Three panes faired in place as necessary.

Steering gear tried under working conditions, by air ~~sent~~ and hand and found satisfactory.

*A. W. Jackson.*

## ANCHORS.

[illegible]

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

## CHAIN CABLES.

[illegible]

Iron Stream Chain }  
or Steel Wire.... }