

2 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Africa Maru

Rpt.

Kokob

No.

7436

Acts of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 3

Survey

This Survey, due 3.30 ~~partly held at~~

now

pleted, and the following repairs carried out (due to damage &):-
wear & tear.

damage caused by propeller striking wharf. Propeller black
and damaged now renewed
the minor wear & tear repairs effected

It is submitted the vessel is eligible to remain as classed, with

tation of

+ Line 7.31

as recommended.

Star. S. 7.31

JRM

17.8.31



© 2021

Lloyd's Register
Foundation

005635-005643-0249

yen 275.00

Fees applied for