

50 102

(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the

5m.7.32.

19 DEC 1932

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Twin Sc.Sr. "AFRICA MARU", Rpt. Kob. No. 7971

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey

MAIN

The class is subject to the topmast be further examined at the Owners' convenience.

The Kobe Surveyors now report the vessel placed in dry dock, bottom cleaned and coated, the deep tank tested and some minor alterations carried out and the fore top mast renewed.

AS APPROVED.

See 1/1

The main topmast examined and found satisfactory.

It is submitted the vessel appears worthy to remain as classed with record of survey 11.32, without special condition.

100A1)
Shelter deck with freeboard) without etc.
11.32 Kob.)
Fitted for oil fuel etc.)



© 2021 Lloyd's Register Foundation

[Handwritten signature]

[Handwritten signature]

16/12/32

005635-005643-0251

Longitudinals.....	cient?	Breasthooks & Stemsom ditto	Anchors, No.
Have Sluice Valves now been examined and found		Transoms Pointers & Crutches ditto	Cables (Sto