

For the information of Surveyors and the Committee only.

Received at ..... Office ..... 19

# Lloyd's Register of Shipping.

(Report on Vessel No. .... Port .....) )

No. .... **SHIP FORGINGS OR CASTINGS.**

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Columbia Steel Company, of Pittsburg, California. for the Vessel No. 18, being built by J. Coughlin & Sons, of Vancouver, B. C. have been inspected by me as set forth below and found to be, so far as can be seen, sound.

Upper section stern frame.

Forgings or Castings.

Lloyd's

No. 673

. 2-20

*W. Lawson*

San Francisco.

	Upper STERN FRAME.	RUDDER FRAME.	STEM.
* .....	<u>O. H. Steel</u>		
ade .....	<u>Cast</u>		
ions .....	<u>as per plan</u>		
is on Inspection .....	<u>rough</u>		
hen Inspected .....	<u>27-1-20 2-2-20</u>		
CASTINGS.			
s on Standard Cast Pieces.	<u>66000</u>		
Test—	<u>63200</u>		
per square inch .....	<u>29</u>		
nsion per cent. ...	<u>34</u>		
ending Test—	<u>120</u>		
le before fracture .....	<u>120</u>		
Test—	<u>9'</u>		
ght from ground ...			
ering Test—	<u>Yes</u>		
ade according to Rules and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) \$ 15.00 :

To be paid at San Francisco.

If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

005644-005655-0120



© 2020

Lloyd's Register Foundation