

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.

19th May, 1916.

Dear Sirs,

With reference to the classification in the Society's Register Book of your S.S. "DARLINGTON", I beg to acquaint you that the Committee have had before them a report received from the Society's Surveyors at Hull of a survey held consequent upon damage sustained through striking a submerged object.

The Surveyors report that two flat keel plates forward were found to be indented and two after keel plates scored. These plates have not now been dealt with, and the Committee have allowed the vessel to remain as classed subject to the necessary repairs being effected at the first opportunity convenient to your goodselves.

I may remind you that the biennial survey of the screw shaft became due at the end of last month.

I am, Dear Sirs,

Yours faithfully

Secretary.

Messrs. The Wilsons & North Eastern  
Railway Shipping Co., Ltd.,

HULL.



Lloyd's Register  
Foundation

005656-005670-0116