

1

MIV

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME BELLEROPHON REPORT Lon. No. 114960AFor the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor..... When due.....

The class is subject to permanent repairs to shell plating etc. (p & s) at the first opportunity.

A Special Survey (C) became due 4,47.

The Owners now state it is not their intention to keep the vessel in Lloyd's classification.

It is submitted the vessel's character be withdrawn from the Register Book and a red line inserted in lieu, indicating non-compliance with the Society's Rules as regards surveys.

Withdraw Class

and insert (4,47)



© 2021 J. Noel

Lloyd's Register
Foundation

005695-005708-0007