

# MITTELMEER

9 OCT 1939

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

'S NAME "MITTELMEER". Rpt. Aru. No. 161.


Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/32.)

The Acting Surveyor at Aruba reports the vessel afloat on account of damage through collision; 2 shell plates on starboard bow found indented and the Surveyor recommends this indented plating be dealt with at the Owners' convenience.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As now, subject etc.

  
9.10.39

Note: . ESD filled 5.38



© 2021

Lloyd's Register  
Foundation

005695-005708-0177