

(F.A.M.)

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

12th September, 1924.

Dear Sirs,

I have to confirm the following cablegrams that
S. have passed between us, regarding the steamer "GASTEIN",

viz.:— Received: "GASTEIN = Name of Vessel
70448 = No. in the Register Book
EHPIT = Owners request
CONSULAR
ENTOB = certificate
EVSOB = for voyage to
EWKUZ = Bombay
EVEVA = Vessel leaving
FELBA = 15th instant.
AWAGA = Bottom
AZPOC = rudder
AZVAD = sea connections
CIJYL = screw shaft
EFGAW = examined
EDPAB = by
EZHYJ = Registro Italiano
AKYJF = in dry dock
EZYWO = last March
EFNUK = found
EGCIF = in order
DIWSY = Plating indented
SLIGHTLY
EKFYX) = to be dealt with
EFAFU)
OWNERS CONVENIENCE
EBTIW = STOP
EHPAR = Owners propose
OPEN
CERBU = engines
BEMNI = boilers
ECVOF = and
AVOBE = hull
EKCAN = survey
ECUCY = afloat
EBONY = Cable whether
ECWYJ = approved
EKMEB) = Vessel has not
EFSOM)

© 2020

Lloyd's Register
Foundation

005740-005755-0218½

COPY.

s.s. "GASTEIN" - Cont.

Cable received - Cont.

"EZHYJ = Registro Italiano
ALZYL = freeboard
ENTOB = certificate
EGNWX = Is
OURS VALID."

Sent:

"GASTEIN = Vessel's Name
EKENX = This
EKMEB = vessel
EFSOM = has not
VALID
AMARP = freeboard assignment
EBTIW = STOP
EGIKS = In view of
DYRAJ = vessel disclassed
EHKYS = only
EKCAN = survey
EKSTE = which
EJTID = should be
EFWEN = held
EJTID = should be
FLIGS = one
EFLAC = for
DUYGH = re-classification."

As you are aware, the class of this vessel was withdrawn from the Register Book at the Owners' request in November last year, and in these circumstances it is considered that the only survey that should be undertaken by you with a view to the issue of a certificate should be one for the re-instatement of the classification.

I am, Dear Sirs,

Yours faithfully,

The Surveyors,

TRIESTE.

Assistant to the Secretary.



© 2020

Lloyd's Register
Foundation