

Am. 6.14

1

Sent to Chief Surveyors

Received from Chief Surveyors

5-MAR. 1923

VESSEL'S NAME

S. S. Royalite

Report

Lon

No. 86890^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

Screw shaft

When due 12. 22.

The screw shaft became due in Dec last—
The Toronto Surveyor now states he is informed
by the Owners that they do not desire to continue
the classification of this vessel as she is to be used
exclusively on the Great Lakes & they carry the insurance
on her themselves.

Submitted this vessel's class be withdrawn from
from the Register Book & three dots inserted in
lieu thereof indicating withdrawal of class at
Owners request—

Withdraw class
Insert (...) *M. C. 2/3/23*



© 2020

Lloyd's Register
Foundation

005756-005778-0017