

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book 71722 Survey held at on the Wood, Iron or Steel &c. Royalite

TONNAGE:- Built at Collingwood Ont. By whom Collingwood S.B. & Co. Ltd. Master When 1916-6

GROSS 225.00 Owners Imperial Oil Ltd. Port belonging to Larina Ont.

NET 154.2 Owners' Address N/W IMPERIAL Destined Voyage WELLAND

Surveyed Afloat or in Dry Dock? Name of Dock WB=CellDBorDBa feet; uE&B feet; total capacity tons. FPT tons; APT tons; MT feet

Last Report, No. 188 Port T/O

Particulars of Classification (which must be inserted in Register Book & Supplements) CHARACTER, etc. for Special Survey. Date of last Survey and of Periodical Surveys.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	
Decks	State if Tanks have been examined inside
Caulking of Decks	State if Tanks now tested
Waterways	Bulkheads
Coamings	Ceiling
Beams & Fastenings	Cement or Asphalt (State which.)
Outside Plating	Rudder
Caulking of ditto	Steering gear and its connections
Rivets	Windlass
Breasthooks & Crutches	Have Pumps now been examined and found efficient?
Transoms	Have Sluice Valves now been examined and found efficient?
Frames	Have Watertight Doors now been examined and found efficient?
Reverse Frames	Have Ventilators and their Coamings been examined and found efficient?
Floors	
Keelsons	
Stringers	
Inner Bottom Plating	
	Dblng. Plates under Sounding Pipes
	Engine Room Skylights
	Coal Bunkers, Open'gs, Lids, &c.
	Scuppers
	Cargo Hatchways
	Hatches
	Planking of Wood Vessels
	Caulking ditto
	Treenails ditto
	Breasthooks & Stemson ditto
	Transoms, Pointers, & Crutches ditto
	Timbers of Frame at openings ditto
	Ditto ditto at other places ditto
	Stringers, Clamps & Shelves ditto
	Salting ditto (State if examined.)
	Copper, or Y.M. of Wood Vessels (State if on Keel.) When put on, Month Year
	Boats
	Masts, Yards, &c.
	Condition, how ascertained (State if wedges removed)
	Sails
	Equipment letter
	Anchors, No. of
	Cables (State if now replaced)
	" length (on board)
	" Rule length
	Hawser & Warps
	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptnd15, &c."

Survey Fee (per Section 20) ...£				Fees applied for, 19...
Special Damage or Repair Fee (if any) (per Sec. 20) ...£				Received by me, 19...
Travelling Expenses (if chargeable) ...£				
Second Surveyor's Fee (if any) ...£				

Committee's Minute TUE. 27 MAR. 1923 Character Assigned Withdraw class decision confirmed

1500-87500-957500 005756-005778-0019