

vic 36

Huich 111342
Leeds 78.

The boiler has been constructed under special survey and in accordance with the approved plan and M.O.W.T. specification.

The machinery has not been constructed in accordance with the requirements of the Rules, but under the Society's supervision.

The machinery and boiler have been installed under the supervision of the Society's Surveyors and in accordance with the terms of the specification.

It is submitted no further action is necessary

005756-005778-0132

Lloyd's Register
Foundation
3/1/84.