

Brown's Shipbuilding & Dry Dock Co., Ltd., Hull.

Yard No.11.

ived by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SSEL'S NAME s.s. "VIC 39" REPORT..... No.....

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This single screw steel lighter for the Admiralty has been built in accordance with approved plans and specification under the supervision of the Society's Surveyors, but is not to be classed.

It is submitted that no action is necessary in this case.



© 2020

Lloyd's Register
Foundation

12.11.43.

005756-005778-0153