

"Vic 39"

Gls. 67269  
Sld. Cert. 30-6-43.

The boiler has been constructed under special survey and in accordance with the approved plan and M.O.W.T. specification.

The machinery has not been constructed in accordance with the requirements of the Rules, but under the Society's supervision.

The machinery and boiler have been installed under the supervision of the Society's Surveyors and in accordance with the terms of the specification.

It is submitted no further action is necessary

005755-005778-0155

© 2020

Lloyd's Register  
Foundation