

10,11.

Richard Dunstan Limited, Thorne. Yard No. 372Sister vessel to "VIC 1", "VIC 2" and "VIC 3"

ived by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SSEL'S NAME VIC 4 Rpt. Hul No. 51526

e remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

This steel steam lighter has been constructed in accordance with approved plans and specification under the supervision of the Society's Surveyors but is not to be classed.

It is submitted that no action is necessary in this case.

f.c.d.
.....
7.3.42



© 2020

Lloyd's Register
Foundation

005756-005778-0184