

1 E

Inspected by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME Vic. 78 REPORT Yes No. 113326

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Compound.If Boilers fitted with forced draught noTail Shaft. If fitted with a continuous liner noIf fitted with an outside gland of } yes.  
approved type

This vessel's machinery ~~appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is~~  
eligible to be classed L.M.C 11.45

NOTE FOR S.R.L.

Approved machinery spare gear  
to be supplied

Y.Rm

10.12.45



© 2020

Lloyd's Register  
Foundation

005756-005778-0277