

of Ship Surveyor

Received from Chief Ship Surveyor

AME *Sted S. S. ORSINO*

Rpt. *Hul*
hull *Hul*

No. *32727*
19th July 21

ks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

vey *Just Entry*

Sub Lt
16.8.21

Submitting the Hull Surveyors be requested to State Whether the Size of
2nd Deck ^{through Amaships} beams is $9 \times 3\frac{1}{2}$ " bulb angle as stated by them or $10\frac{1}{2} \times 3\frac{1}{2}$ " bulb angle
approved and as fitted in the Sister Vessels.

Should also be requested to State Whether the frame spacing forward of the $\frac{3}{5}$ Length
in the peaks is 28" as reported or $27\frac{1}{2}$ " & $28\frac{1}{2}$ " respectively as approved and
the Sister Vessels

Hull 15/8/21



© 2020

Lloyd's Register
Foundation

005791-005810-0358