

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified

2m, 12.25. Subject to No. 1 tank being examined internally at first convenient opportunity & some indented bottom plating faired at Owners' convenience.

3

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor 29 JUL 1927

VESSEL'S NAME *Stl. S. S. ASUKA MARU* Rpt. *Kob* No. *5755*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey *A S.S. No. 3 AND DAMAGE.*

Damage through *stranding*
now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	<i>71</i>	<i>39</i>	<i>5</i>	<i>97</i>	<i>3 post</i>		
Removed and faired or repaired.....	<i>38</i>	<i>51</i>	<i>4</i>	<i>19</i>	<i>9</i>		<i>9</i>
Faired or repaired in place.....	<i>28</i>	<i>25</i>	<i>1</i>	<i>31</i>	<i>13</i>	<i>4</i>	<i>18</i>

Other items:- *Vessel placed in drydock, bottom coated Minor repairs & STB tanks exam'd internally & placed in good condition*

The *A S.S. No. 3* has also been held ~~and following repairs done~~ due to wear and tear:- *Deep tanks for the carriage of oil fuel &c. have been fitted forward of the machinery space, in accordance with plans approved at Kobe. & Sec 35 of the Rules complied with*

It is submitted the vessel is worthy to remain as classed with record of Survey *5. 27* and notation of *S. S. No. 3 - 5. 27* as recommended. *without condition*

100 A. 1. 5. 27 Osa } Without etc. 5. S. No. 3 - 5. 27



© 2021 Lloyd's Register Foundation

45 Insert DT of 13865 in R.B.

28.7.27

8100-08485000-078500